



South side of building Dec 7th after explosion



North side of building Dec 7th after explosion




Outside of building across street Dec 7th



Inside of building across street Dec 7th




My office, some ceiling tiles down, notice cracks on wall, left side is 3" behind right side




Receiving dock doors – blown out by explosion



John L's office ceiling



John L's office



View from Tollway Overpass 12-10



View from Oasis 12-12